Superfund file



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION VI 1445 ROSS AVENUE, SUITE 1200 DALLAS, TEXAS 75202

DATE:

4-16-91

MEMORANDUM

SUBJECT: Potential Hazardous Waste Site - Site Inspection Report

FROM:

0. Thomas Love, Jr., P.E.

Acting Chief

Water Supply Branch (6W-S)

TO:

Betty Williamson

Chief

Superfund Management Branch (6H-M)

In response to the CERCLA investigation reports which you recently sent to the Water Supply Branch, I am attaching our comments. Thank you for the opportunity to review these documents.

..ctachment:

Site Name: Umayaf Company

Site Location: I fan Untertio

cc: Carl Hickam (6H-ES)

SUPERFUND FILE

OCT 26 1992

REORGANIZED

INSPECTION REPORT REVIEW POTENTIAL HAZARDOUS WASTE SITE

FOIENTIAL HAZARDOUS	WASTE SITE	
SITE NAME : AMAYOL COMPANY		
LOCATION : SAN ANTONIO		
SITE NUMBER: TXD008113414		
SURVEY DATE: 1991 INSPECT D BY:	STATE (FIT) TA	T OTHER:
LABORATORY :CLPEPAOTHER_		
RECEIVED FROM: BILL TAYLOR	DATE	RECEIVED: 3/18/1
SAMPLE TYPE(s):		
SOIL SURFACE WATER	GROUND WATER	DRINKING WATER
off / on -site off / on -site	off / on -site	off / on -site
CONTAMINANT(s): Organics Inorganics	Radionuclides	Microbiological
FOLLOW UP (Y/N):		
	ite Drinking Wate	
		"-No Further Action)
N Further Action is URGENT Y Conc	cur with Report F	Recommendations
SUMMARY:		
This is a Superfund Site Strategy Recomm		
cancellation for the Amayol Company site		
recommended no further action under Sup of the preliminary assessment planned for		ludes the cancellation
The FIT conducted an on-site recon of t		
Information could not be found on the site		, disposal, or busines
nature, in spite of a thorough record re	eview.	
RECOMMENDATION:		
We require no further action.		

Concurrence:
Flower Noves + 16,7 ENGINEER/REVIEWER

ENGINEER/REVIEWER